

RENEW  $\frac{1}{4}$  S13 | S18 T30S  
R7W R7W

FOUND - BOTH ORIG. BTS. AS  
RECORDED. SEE BT PREVIOUSLY  
OPENED SHOWS GOOD SCRIBING.  
"1/4 S"

SET BRASS CAP AT CORNER  
MND. COUNTY SURVEYORS OFFICE  
1962  $\frac{1}{4}$  S13 | S18 T30S  
R7W R7W

NOTE - BOTH BTS. IN GOOD CONDITION  
DO NOT SCRIBE NEW BTS.

RENEW  $\frac{1}{4}$  COR.  $\frac{3}{10}$  T29S R7W

FOUND - ORIG. 12" NOW 20" B. OAK  
N23°W 9.9' PREVIOUSLY OPENED  
SHOWS GOOD SCRIBING  $\frac{1}{4}$ "  
ORIG. SW BT NOW DOWN  $\frac{1}{4}$ " ROTTED

SET BRASS CAP AT COR. MND,  
COUNTY SURVEYORS OFFICE 1962  
 $\frac{1}{4}$  S3 | T29S R7W  
S10

NEW BTS.  
RESURIBE 20" B. OAK N23°W  
9.9'  $\frac{1}{4}$  S3 CS BT

11" R.F. IR BEARS 537  $\frac{1}{2}$  E 358  
SCRIBED  $\frac{1}{4}$  S10 CS BT.

NOTE - COR. IS ON EAST SLOPE  
ABOUT 15' EAST OF TOP OF SPUR  
THAT BEARS N45°E.

+ \* ✓

C.S. File No. 49/139-93