

Review $\frac{1}{4}$ COR. S2 T51 T, 295, R, 7W.
Fd. Remains of old Fence cor. at
COR. point with only Traces of
fences N. & E. & B.T.s as Recorded
in Rev. # 19 as follows -

30" Now 38" Fir N, 30° E, 30 ft
Now sawed stump - "CS BT" Bark
Scribe in very poor cond.

18" Now 24" Fir N, 86° W 27.5 ft,
Record S.W. - No scribe Fd. - sawed
stump - Too low - at COR. point
set 1" I.P. & Brass cap MKd

"COUNTY SURVEYORS OFFICE
1969 T295 $\frac{1}{4}$ S2 | 51 R7W" & MK.
New B.T.s -

28" D. Fir N, 31° E, 58.5 ft,

Mkd. " $\frac{1}{4}$ S1 CS BT"

13" D. Fir N, 53° W, 53 ft.

Mkd. " $\frac{1}{4}$ S2 CS BT"

This cor. Lies on Steep Southerly Slope
very sparsely covered with D. Fir &
Dense Brush -

March 6, 1969

~~#186~~ P. Tracy

V.R.J.
F.W.J.
V.P.

G.H.
J.W.B.
- 121

C.S. File No. 49/139