

S.E.
DLC #90

Renewal #58

T29S R1W

Found -

As noted oak N29W 26 $\frac{1}{2}$ (orig)
Possible old P.C. mark

13" D. Fir New stump South 35 $\frac{1}{2}$
Scribe visible BT

16" D. Fir New stump N29W 52 $\frac{1}{2}$
Scribe visible BT

Also 5 $\frac{1}{8}$ " I rod at cor (Best)

Renewal

Set Brass cap at P.C. cor Mkt
county surveyors office

S.E.
DLC #90

1970

New Bearing Trees

7" D. Fir N15W 51 $\frac{1}{2}$
Scribed SE DLC 90 CS BT

11" D. Fir S6W 17 $\frac{1}{2}$
Scribed SE DLC 90 CS BT

Note:

This cor lies on Top of ridge
on South side of old Rd. 19° North
& 32° West to center of Rd.
Also cell of 2 cabins seems to
fit good also appears to line up
with N-S line in valley to the south.

D.H.
J.W.D.

10-19-70
~~_____~~

#194

C.S. File No. 49/139-132

DIETZGEN NO. 385-6