

Not Found. 9/10 7293 R6W.

Reputed by Markham 1953-#91

orig. LT 29" SO. 365W 587°

Not Found.

10" Pipe N23W 166° Not FD

I come off SE cor of
Cemetery given bearing & dist
I miss the dist to the
Willis creek rd. (approx 125°)
(3-5-71) J.W.P.

I look for iron pipe for
cor with Metal Finder with
no results. Cor falls in
large field probably
removed by cultivation.

J.W.P.

O.K.
J.W.P.

CS 49/139-142

C.S. FILE NO.