

REN. T 21 S R 6 W

17/16
20/21

FD. ROTTEN FIR SNAG

N 15° W 44 FT. (INSTEAD OF 47⁵ FT)

GOOD BARK SCRIBING VISIBLE "T 21 S R 6 W S 17"

FD. FIR TREE (NOW 68" DIAM.)

N 14° E 22⁴ FT (TO FACE), TRACES OF FAINT BARK SCRIBING VISIBLE. "S" IS

ALL I CAN RECOGNIZE. BLAZE & RESCRIBE THIS TREE "T 21 S R 6 W S 16 CS BT"

FD. HEMLOCK TREE (NOW 42" DIAM.)

S 69° E 10⁶ FT. (TO FACE) BLAZE & RESCRIBE "T 21 S R 6 W S 21 CS BT"

NO TRACE OF S.W. B.T. FD.

AT COR. SET IRON PIPE WITH BRASS CAP MKD "COUNTY SURVEYOR'S OFFICE

1961 T 21 S R 6 W S 17/S 16"

S 20/S 21

BLAZE & SCRIBE TWO NEW TREES:

11" HEMLOCK N 68° W 101⁵ FT. MKD,

"T 21 S R 6 W S 17 CS BT"

17" HEMLOCK S 67¹/₂° W 73⁰ FT MKD,

"T 21 S R 6 W S 20 CS BT"

NOV. 13, 1961

M.G.
V.T.
C.P.

Milo E. Godfrey

C. S. File No. 49/143-10

+ * O