

REM.

T 21 S R 6 W

2 | 1

11 | 12

FD. HAINES' "T" IRON AT
COR.

FD. FIR STUMP (NOW 16" DIAM.)
S 11° E 18 1/2 FT. (SLOPE DIST.) HAD
BEEN PREVIOUSLY OPENED. GOOD
SCRIBING "BT" VISIBLE.

FD. ROTTEN REMAINS OF FIR STUMP
N 74° E 11 1/2 FT. (SLOPE)

FD. ROTTEN REMAINS OF FIR STUMP
S 41° W 25 1/2 FT. (SLOPE)

FD. ROTTEN REMAINS OF FIR STUMP
N 18° W 17 1/2 FT. (SLOPE). LAST THREE
STUMPS TOO FAR GONE - NO SCRIBING FD.

ALONGSIDE "T" IRON AT COR. SET IRON
PIPE WITH BRASS CAP MKD. "COUNTY SUR-
VEYOR'S OFFICE 1961 T 21 S R 6 W

S 2 | S 1

S 11 | S 12

BLAZE & SCRIBE NEW TREES:

7" FIR S 67° W 33 1/2 FT. MKD.

"T 21 S R 6 W S 11 CS BT"

26" FIR S 13 1/2° E 33 0 FT. MKD.

"T 21 S R 6 W S 12 CS BT"

7" FIR N 56° W 20 3 FT. MKD. "T 21 S

R 6 W S 2 CS BT"

9" LAUREL N 17° E 23 1/2 FT. MKD.

** T 21 S R 6 W S 1 CS BT"

C.S. File No.

49/143-12

DEC, 12, 1961

M. G.
V. T.
C. P.

Mills & Co
Surveyors

DIETZGEN NO. 385-6

FILED
RECEIVED

DEC 12 1961

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.