

REM. T 21 S R 6 W $\frac{1}{4}$ S $\frac{1}{2}$ S
312

FD. FIR STUMP (NOW 47" DIAM.)

S 55° E 10 $\frac{6}{8}$ FT. OPENED SCAR & FD.
FRAGMENT OF SCRIBING - BOTTOM OF
SCAR IS ALMOST AT TOP OF STUMP

FD. FIR TREE (NOW 36" DIAM.)

S 67° W 9 $\frac{3}{8}$ FT. (TO FACE). SHOWS GOOD
SCAR AT BOTTOM. - TREE HAS BEEN
RESCRIBED (IN BARK) " $\frac{1}{4}$ S BT" BLAZE
& RESCRIBE THIS TREE (ONE SCAR) " $\frac{1}{4}$ S
3 CS BT." DIST. TO CENTER OF TREE 10 $\frac{5}{8}$ FT.
BEARING O.K.

AT COR, SET IRON PIPE WITH BRASS CAP

MKD. COUNTY SURVEYOR'S OFFICE 1961

T 21 S R 6 W $\frac{1}{4}$ S $\frac{1}{2}$ S
312

BLAZE & SCRIBE ONE NEW TREE:

6" HEMLOCK N 52 $\frac{1}{2}$ ° E 24 $\frac{7}{8}$ FT.

MKD. " $\frac{1}{4}$ S 2 CS BT"

Milo E. Hoffrey

DEC. 28, 1961

M.G.

V.T.

C.P.