

REN. T22S R6W

6/5  
7/8

AT COR. FD. 3/4" X 14" IRON ROD,

FD. FIR TREE (NOW 23" DIAM.)

S 23° E 11 1/2 FT. - SHOWS GOOD SCAR.

BLAZE & RESCRIBE "T22SR6W S8

CS BT."

FD. SHORT FIR SNAG (18" DIAM.)

N 63° E 23 1/4 FT. SCRIBING VISIBLE

"S5 22S."

FD. ROTTED FIR SNAG S 44° W

23 1/4 FT. GOOD SCAR BUT NO SCRIBING

FD. - FACE ROTTED AWAY.

FD. STUMP HOLE N 59° W 19 1/4 FT.

ALONGSIDE IRON ROD AT COR. SET

IRON PIPE WITH BRASS CAP MKD.

"COUNTY SURVEYOR'S OFFICE 1961

T22S R6W 56/55"

57/58

RESCRIBE S.E. B.T. (SEE ABOVE)

BLAZE & SCRIBE NEW TREE:

26" DOUG. FIR N 41° E 21 1/4 FT. MKD.

"T22SR6W S5 CS BT."

NO OTHER TREES NEAR.

*Milo C. Griffin*

SEPT. 13, 1961

M.G.

C.S. FILE NO. 19/143

C.P.

\* + OXV

-77