

REN. T 22 S R 6 W $\frac{1}{4}$ $\frac{S4}{S9}$
FD $\frac{3}{4}$ " BOLT AT COR. WITH 1" SQUARE
HEAD.

FD. ROTTEN STUMP OF FIR N 14° E
91' FT. FD. GOOD SCRIBING "BT."
FD. BADLY BURNED FIR STUMP
S 20° E 35' FT. SHOWS EVIDENCE OF
HAVING BEEN OPENED PREVIOUSLY. NO
SCRIBING FD.

ALONGSIDE BOLT AT COR. SET IRON
PIPE WITH BRASS CAP MKD. "COUNTY SUR-
VEYOR'S OFFICE 1961 T 22 S R 6 W $\frac{1}{4}$ $\frac{S4}{S9}$ "

BLAZE & SCRIBE NEW TREES:

10" DOUGLAS FIR N 12° W 137' FT.
MKD. " $\frac{1}{4}$ S4 CS BT"

9" WHITE FIR S 14° E 113' FT.
MKD. " $\frac{1}{4}$ S9 CS BT"

SEPT. 29, 1961

M.G.
V.T.
C.P.
J.P.

Milo C. Godfrey