

Renewal

11/12  
1A/13

T225 R6W

Found

2" I.P.P. at Sec. E.P.T.

Tied From Survey CS File  
43/112

Renewal

Set Brass cap along side I.P. MARK  
County Surveyors office

T225 R6W

511 512  
514 513

1968

New Bearing Trees

8" P. Fir N 34 E 31 1/2  
Scribed T225 R6W 512 CS BT

28" Maple N 25 W 19 1/2  
Scribed T225 R6W 511 CS BT

1 1/2" P. Fir S 50 W 7 1/2  
Scribed T225 R6W 514 CS BT

P. Pole # 6-54 S 59 E 19 1/2

P.K. Nail in Base of Pole

7-13-68

~~James  
[Signature]~~

5120

O.K. J.V.B.

C.S. File No. 49/112

DIETZGEN NO. 385-6

Tie From Highway Pkwy  
 Rods CS 13/142

DIETZGEN NO. 385-6

7223 R6W

11/12

14/13

FD 2" I P. P. C.

209° 10'  
 104° 35'

ELK CURS



42.32'  
 255' 11"

213° 36'  
 95° 38'

257° 17'  
 41° 53'

216 67

168° 48'  
 84° 24'

170° 06'  
 87° 33'

FD 3/8" I Rod  
 AD 1/2" I Rod  
 AD 5/8" I Rod

182 52

AD 5/8" I Rod

3 99  
 11/12

S. File No. 49/143 (29)

USE CS 43/142