

Review Standard Cor. T22 S  
56155 T235 R6W

Fd. 1955 cad. BRASS cap nearly out of ground & properly MKd. we

Reset from following B.T.S -

ORIG. 54" FIR S. 25° E. 53 ft.

Now STUMP - Blaze BURNED -

<sup>①</sup> 1955 16" now 17" Hemlock S. 29° E 52 ft.

Now BROKEN off 8 ft. above ground.

Record dist 31 ft. <sup>③</sup> NO TRACE

of OTHER B.T.S - <sup>④</sup> We MK. New

BT -

16" Hemlock N. 28° E. 18 ft.

Mkd. " SC CS BT "

No TREES south of cor. - This

cor. Lies on Steep Northerly

Slope approx. 100 ft. South

of Squaw creek course West.

Dec. 23, 1969

U.R.T.  
J.G.H.  
V.D.P.

*U.R.T. Tracy*

*01 V  
J.W.B.*

9122  
157-125-6

C. S. File No. 92/102-100