

# THE ROBERT DOLLAR CO.

COW CREEK DIVISION  
GLENDALE, OREGON

TELETYPE GLENDALE 85

TELEPHONE 521

December 28, 1959

Douglas County Surveyor  
County Courthouse  
Roseburg, Oregon

Dear Sir:

The north quarter corner of Section 4, T 32 S, R 8 W, W. M. was found to be in poor condition. The original bearing trees are still here but the scribing has nearly all rotted away. Since the original bearing trees are madrona, I scribed two new bearing trees and marked the corner as follows:

The corner was marked with a 1 $\frac{1}{2}$ " (O.D.) iron pipe driven 18" into the ground. A 12" Douglas Fir, S 39 $\frac{1}{2}$ <sup>o</sup> E, 45.3 feet, was referenced and scribed S4,  $\frac{1}{4}$ S, 4186 B.T. A 9" Ponderosa Pine, N 22<sup>o</sup> E, 52.3 feet, was referenced and scribed S 33  $\frac{1}{4}$ S, 4186 B.T.

Bearing trees were referenced with a compass and chain. Magnetic declination used was 19 $\frac{1}{2}$ <sup>o</sup> E. Witnessed by Robert Harris and Milner Larson.

Yours very truly,

THE ROBERT DOLLAR CO.



Lorne Swearingen  
Registered Engineer 4186

LS/jvd