

# THE ROBERT DOLLAR CO.

COW CREEK DIVISION  
GLENDALE, OREGON

TELETYPE GLENDALE 85

TELEPHONE 521

April 13, 1960

Douglas County Surveyor  
County Courthouse  
Roseburg, Oregon

Dear Sir:

The corner common to Section 10, 11, 14 and 15, T 32 S, R 8 W, W. M. was found in very poor condition. The bearing trees for Sections 10, 14 and 15 were Fir snags which had been bark scribed and a fire had destroyed the scribing on all except the tree for Section 14 which had some scribing visible. The bearing tree for Section 11 had been a Laurel but only a stub remained.

I set the corner from the remaining evidence and marked it with a 1 $\frac{1}{4}$ " (O.D.) iron pipe driven 20" in the ground from which I referenced a 30" Douglas Fir N 68 $\frac{1}{2}$ ° E 74.3 feet marked S 11, 4186 BT, a 6" Tan Oak S 62 $\frac{1}{4}$ ° E 30.4 feet marked S 14, 4186 BT, a 36" Douglas Fir S 11° W 58.2 feet marked S 15, 4186 BT, a 8" Tan Oak N 63 $\frac{1}{2}$ ° W 9.6 feet marked S 10, 4186 BT.

Bearing trees were referenced with a compass and chain, magnetic declination 19 $\frac{1}{2}$ ° E. Witnessed by Robert A. Harris and Milner Larson.

Yours very truly,

THE ROBERT DOLLAR CO.



Lorne Swearingen  
Registered Engineer 4186

LS/jvd