

# THE ROBERT DOLLAR CO.

COW CREEK DIVISION  
GLENDALE, OREGON

TELETYPE GLENDALE 85

TELEPHONE 521

April 13, 1960

Douglas County Surveyor  
County Courthouse  
Roseburg, Oregon

Dear Sir:


The quarter corner common to Section 13 and 24, T 32 S, R 8 W, W. M. was found in poor condition. The bearing tree for Section 13 is still in good condition. The bearing tree for Section 24 was a 40" Sugar Pine which evidently had been bark scribed and had been felled in a clear cut logging operation.

I marked the corner with a 1 $\frac{1}{4}$ " (O.D.) iron pipe driven 20" in the ground. An 8" Douglas Fir S 34° E 25.3 feet was referenced and scribed S 24, AS 4186 BT.

This bearing tree was referenced with a compass and chain. Magnetic declination was 19 $\frac{1}{2}$ ° E, witnessed by Robert A. Harris and Milner Larson.

Yours very truly,

THE ROBERT DOLLAR CO.



Lorne Swearingen  
Registered Engineer 4186