



# THE ROBERT DOLLAR CO.

## LUMBER PRODUCTION DIVISION

TELETYPE 39 • TELEPHONE VEron 2-5810  
GLENDALE, OREGON

SAN FRANCISCO 4  
HEAD OFFICE  
311 CALIFORNIA STREET  
NEW YORK 4, NEW YORK  
1 BROADWAY  
WASHINGTON 6, D. C.  
716 TRANSPORTATION BUILDING

May 20, 1960

Douglas County Surveyor  
County Courthouse  
Roseburg, Oregon

Dear Sir:

The quarter corner common to sections 16 and 21, T32S, R8W, W.M. was found to be in poor condition. The original stone for the corner was gone but both original bearing trees remain. The called distances and bearing would not fit to set the corner unless the original distance to the North bearing tree was used as a slope distance.

I set a 1" (I.D.) iron pipe for the corner. Although the original bearing tree S10°E, 6 lks. distance is a stump with bark scribing visible, the bark is very loose and original evidence will be lost in the near future, so I scribed a new 12" Fir, S19°W, 24.9 ft. distance and marked S21½S. B.T. The North bearing tree still has a very little bark scribing visible, but it may be gone in a few years so I rescribed original bearing tree in the wood as follows: a 28" Fir North 24.9 ft. distance (original called for 30.4' but I used this as slope distance) scribed S16½S 4186 B.T.

Bearing trees were referenced with a compass and chain magnetic Declination used was 19½E. Witnessed by Robert A. Harris and Milner Larson.

Yours very truly,

THE ROBERT DOLLAR CO.

*Lorne Swearingen*  
Lorne Swearingen  
Registered Engineer 4186

LS/bf