



THE ROBERT DOLLAR CO.

LUMBER PRODUCTION DIVISION

TELETYPE 39 • TELEPHONE VERNON 2-5810

GLENDALE, OREGON

May 20, 1960

SAN FRANCISCO 4
HEAD OFFICE
311 CALIFORNIA STREET
NEW YORK 4, NEW YORK
1 BROADWAY
WASHINGTON 6, D. C.
716 TRANSPORTATION BUILDING

Douglas County Surveyor
County Courthouse
Roseburg, Oregon

Dear Sir:

The quarter corner common to sections 16 and 17, T32S, R8W, W.M. was found in poor condition. The original bearing tree for section 16 is still in good condition, with scribing plainly visible. The original bearing tree for section 17 was gone.

I set a 1" (I.D.) iron pipe, driven 20" in the ground (set from original bearing tree in section 16) for the corner. I scribed a 20" live oak new bearing tree N72 $\frac{1}{2}$ °W, 23.3 feet distant marked S17 $\frac{1}{4}$ S 4186 B.T.

This bearing tree was referenced with a compass and chain magnetic declination was 19 $\frac{1}{2}$ °E witnessed by Robert A. Harris and Milner Larson.

Yours very truly,

THE ROBERT DOLLAR CO.

Lorne Swearingen
Registered Engineer 4186

LS/bf