

# THE ROBERT DOLLAR CO.

COW CREEK DIVISION  
GLENDALE, OREGON

TELETYPE GLENDALE 85

October 7, 1960

TELEPHONE 521

Douglas County Surveyor  
County Courthouse  
Roseburg, Oregon

Dear Sir:

The section corner common to Sections 19, 20, 30 and 29, Township 32 South, Range 8 West, W. M. was found to be missing. All bearing trees were missing except the original S.E. bearing tree, which is in very poor shape but has some original scribing visible.

I set a 7/8" X 30" Hex. drill steel driven 20" in the ground for the corner. I scribed four new bearing trees as follows: a 6" Fir N42° W 13.2 feet and scribed T 32 SR8WS194186 B.T.; a 4" Tan Oak N35° E 19.1 feet and scribed T 32 S R8W S20 4186 B.T.; a 10" Sugar Pine S 20° E 32.6 feet and scribed T 32 S R8W S29 4186 B.T.; a 6" Laurel S 24° W 28.5 feet and scribed T 32 S R8W S30 4186 B.T. ✓✓

The quarter corner common to Sections 5 and 6, Township 32 South, Range 8 West, W. M. was found to be missing. One original B. T. remains with scribing visible but the tree (12" Tan Oak) is nearly rotted down.

I set a 7/8 X 30" hex drill steel driven 20" in the ground for the corner. I scribed two new bearing trees as follows: a 8" Fir N 30° E 18.3 feet and scribed S 5 1/4 S 4186 B.T.; a 22" Fir S52 1/2 W 37.2 feet and scribed S 6 1/4 S 4186 B.T. ✓✓

Bearing trees were referenced with a compass and chain, magnetic declination used was 19 1/2° E. Witnessed by Robert A. Harris and Milner Larson.

Yours very truly,

THE ROBERT DOLLAR CO.

*Lorne Swearingen*

Lorne Swearingen  
Registered Engineer 4186

FILED  
RECEIVED

OCT 11 1960 LS/jvd

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C. S. File No. 51/63 - 8