



# THE ROBERT DOLLAR CO.

## LUMBER PRODUCTION DIVISION

TELETYPE 39 • TELEPHONE VERNON 2-5810

GLENDALE, OREGON

May 2, 1960

SAN FRANCISCO 4  
HEAD OFFICE  
311 CALIFORNIA STREET  
NEW YORK 4, NEW YORK  
1 BROADWAY  
WASHINGTON 6, D. C.  
716 TRANSPORTATION BUILDING

Douglas County Surveyor  
County Courthouse  
Roseburg, Oregon

Dear Sir:

The section corner common to Sections 4, 3, 9 and 10, Township 31, S., Range 9 W., W.M. was found to be missing. All bearing trees were found and in good condition. I set a 7/8" x 30" Hex drill steel driven 20" in the ground for the corner. ✓

The quarter corner common to Sections 4 and 3, Township 31, S., Range 9 W., W.M. was found to be missing. Both bearing trees were found with scribing visible. I set a 7/8" x 30" Hex drill steel driven 20" in the ground for the corner. ✓

Very truly yours,

Lorne Swearingen  
Registered Engineer 4186

LS:mt

FILED  
RECEIVED

MAY 4 1960

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C. S. File No. 51/60-13