



THE ROBERT DOLLAR CO.

LUMBER PRODUCTION DIVISION

TELETYPE 39 • TELEPHONE VErnon 2-5810

GLENDALE, OREGON

SAN FRANCISCO 4
HEAD OFFICE
311 CALIFORNIA STREET
NEW YORK 4, NEW YORK
1 BROADWAY
WASHINGTON 6, D. C.
716 TRANSPORTATION BUILDING

May 20, 1960

Douglas County Surveyor
County Courthouse
Roseburg, Oregon

Dear Sir:

The quarter corner common to sections 21 and 22, T 31S, R9W, W.M. was found in poor condition. A severe fire has burned this area, which probably took place soon after the original survey. I found the original bearing tree for section 21 in, and opened the remains of the old face and have found definite markings of the old scribing visible, but because of the condition of the face and snag this may be gone in the near future.

I set a 7/8" x 30" Hex drill steel for the corner, driven 20" in the ground. 96" fir N29½°W, 16.8 feet was referenced and scribed S21½°S 4186 B.T. A 6" fir N35°E 41.1 feet was referenced and scribed S22½°S 4186 B.T.

These bearing trees were referenced with a compass and chain: Magnetic declination was 19½°E, witnessed by Robert A. Harris and Milner Larson.

zYours very truly,

THE ROBERT DOLLAR CO.

Lorne Swearingen
Lorne Swearingen
Registered Engineer 4186

LS/bf

✓✓ C. S. File No. 51168-4