

T. 25 & 26 S., R. 3W., W. M.

Renewal of $\frac{1}{4}$ corner, sections 36 and 1.

At this $\frac{1}{4}$ corner I found the brass cap monument destroyed and the two bearing trees had been felled.

I determined the true point of the corner from the stumps of these trees, and at this point I drove a 2 inch iron pipe 30" long, 18" in the ground, from which;

A hemlock 30 inches in diam. bears N. 53° E. 17.6 ft.
marked $\frac{1}{4}$ S. 36 253 B. T.

A tan-oak 6 inches in diam. bears S. 19° E. 20.9 ft.
marked $\frac{1}{4}$ S. 1 253 B. T.

Dec. 29, 1960



FILED
RECEIVED

JAN 3 1961

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

✓✓✓✓

C. S. File No. 51/161