

The following corners have been renewed for Roseburg Lumber Co.

1/4 corner between sections 25 and 36, T31S R7W  
Found: 20 in. Fir N5E (now a snag bark scribe visible)  
24 in. Fir S40E (faint bark scribe)  
Set: 1 in. by 30 in. iron pipe  
Scribed: 22 in. D. Fir N59E 42.8 ft.  
Rescribed the original BT S40E ○ + ✓

\*\*\*\*\*

Section corner for sections 25, 26, 35, & 36 T31S R7W  
Found: 4 good BT's renewed in 1957  
Set: 1 in. by 30 in. iron pipe. ○ + ✓

\*\*\*\*\*

1/4 corner for sections 26 and 35 T31S R7W  
Found: original BTs in good condition  
Set: 1 in. by 30 in. iron pipe. ○ + ✓

\*\*\*\*\*

1/4 corner between sections 23 and 26 T31S R7W  
Found: 12 in. Fir N10E 5.3 ft.  
Set: 1 1/4 in. by 40 in. iron pipe.  
Scribed: 20 in. D. Fir S76W 74.9 ft.  
15 in. W. Fir N76E 52.0 ft. ○ + ✓

\*\*\*\*\*

1/4 corner between sections 25 and 26 T31S R7W  
Found: Live Oak N32W 56.1 Ft. good condition  
S. Pine S10E 55.4 ft. now 60 in. snag  
Set: 1 in. by 30 in. iron pipe  
Scribed: 6 in. D. Fir S70 1/2 E 11.0 ft. ○ + ✓

\*\*\*\*\*

Section corner for sections 34 and 35 T31S R7W and sections 2 and 3  
T32S R7W  
Found: 26 in. Fir N54W 71.9 ft. (now 46 in. good condition)  
8 in. Laurel N12E 46.9 ft.  
14 in. Laurel S60W 4.0 ft. (stump)  
Set: 1 in. by 36 in. iron pipe  
Scribed: 16 in D. Fir S35E 44.4 ft.  
14 in. D. Fir S78W 65.0 ft.  
12 in. D. Fir N36E 53.6 ft. ○ ○ + ✓

\*\*\*\*\*

1/4 corner between sections 25 T31S R7W and section 30 T31S R6W  
Found: original BTs in good condition  
Set: 1 in. by 30 in. iron pipe. ○ ○ + ✓

\*\*\*\*\*

1/4 corner between sections 22 and 27 T31S R7W  
Found: 50 in. Fir N54E 20.5 ft. (now 60 in. snag, bark scribed)  
16 in. Fir S16W 15.8 ft. (now 38 in.)  
Set: 1 in. by 30 in. iron pipe  
Scribed: 12 in. D. Fir S63 1/2 W 28.2 ft.  
19 in. D. Fir N22 1/2 W 63.0 ft. ○ + ✓

REGISTERED  
OREGON  
LAND SURVEYOR

*Howard W. Johnstone*

MAY 13, 1960  
HOWARD W. JOHNSTONE  
498

ROYALTY SURVEYOR  
LAND SURVEYOR