

The following Corners have been renewed for Roseburg Lumber Co. :

T30S, R8W, quarter corner common to sections 23 and 26:

found: 12 in. Fir with $\frac{1}{4}$ S on north face (now a stump),
set: 1 in. x 30 in. Iron Pipe on north side of stump.
found: 27 in. Fir N01 $\frac{1}{2}$ E 49.7 ft. (now a badly burned stump, its
scribe not discernable), rescribed this stump $\frac{1}{4}$ S BT S23.

Fir S50W 96.1 ft. is now a stump, scribe in good condition. \odot
Note: this corner falls in the middle of a logging unit and there are
no standing trees for new bearing trees.

T30S, R8W, quarter corner common to sections 14 and 23:

found: 12 in. Cedar N25E 9.9 ft. (down, scribe visible).

set: 1 in. x 36 in. Iron Pipe
5 in. White Fir S70W 55.8 ft. $\frac{1}{4}$ S 23 BT.
13 in. Doug. Fir N80 $\frac{1}{2}$ E 23.0 ft. $\frac{1}{4}$ S 14 BT. \oplus

T30S, R7 & 8W, section corner common to sections 18 & 19 R7W and 13 & 24 R8W:

could not locate the original corner stone.

found: 8 in. Fir N72W 9.9 ft.
17 in. Fir N38E 34.3 ft.

set: 1 in. x 30 in. Iron Pipe in stone mound.
12 in. Fir S69 $\frac{1}{2}$ E 53.0 ft. \oplus
15 in. Fir S37W 68.5 ft. \oplus

T31S, R7W, section corner common to sections 26, 27, 34, and 35:

found: 24 in. Laurel S33E 54 lks. (scribe visible)
44 in. Fir S85W 20 lks. (stump)
28 in. Fir N15W 14 lks. (stump)

set: 4 x 4 x 48 in. cedar post
20 in S. Pine N80 $\frac{3}{4}$ E 35.5 ft.
14 in. S. Pine S08 $\frac{1}{2}$ E 20.0 ft.
4 in. Fir S25 $\frac{1}{2}$ W 17.5 ft.
12 in. Red Cedar N83 $\frac{1}{2}$ W 20.5 ft.

FILED
RECEIVED

OCT 5 1961

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

\oplus

T30S, R9W, quarter corner common to sections 14 and 23:

found: 6 in. Chinkipin N60W 29.0 ft. (dead)
38 in. Doug Fir S66W 7.9 ft. (now a stump, scribe good condition)

set: 1 in. x 30 in. Iron Pipe
17 in. Doug Fir N10E 93.5 ft. \oplus

Witness:

R. J. Henrikson

Jerry Clark

September 15, 1961

REGISTERED
OREGON
LAND SURVEYOR

Howard W. Johnstone
MAY 13, 1960
HOWARD W. JOHNSTONE
498

C.S. No. 51/163⁵