

**ROBERT M. THOMPSON**  
Consulting Engineer and Forester

RENEWAL OF 2- $\frac{1}{2}$  CORNERS ON RANGE LINE, SECTIONS 31 & 36, T32S,  
R8W & R9W, W.M.

At EAST  $\frac{1}{4}$  Corner Sec. 36/ only,

I find 3/4" I. P. with brass cap. from which A;

20" D. Fir bears S72°W, 67 Lks (O.B.T.)  
(Now 30" cut stump)

8" D. Fir, N35°W, 33 LKS (O.B.T.)  
(Now 12" and down)

TO RENEW I SCRIBE A;

6" D. Fir, S67°W, 28.4 feet  $\frac{1}{4}$ S36 BT"  
6" D. Fir, North, 9.6 ft.

No other trees within reasonable distance.

At WEST  $\frac{1}{4}$  Corner Sec./31 only

I find 1" I.P. with brass cap, from which a

18" D. Fir (now 20") bears N72°E, 58 Lks (O.B.T.)  
12" D. Fir, S86°E, 74 lks now 16" cut stump

TO RENEW I SCRIBE A

9" D. Fir, N35°E, 18.5 ft.  $\frac{1}{4}$ S 31 BT"

✓ WITNESS: R. GLEDHILL

Feb. 28, 1961

FILED  
RECEIVED

MAR 5 1961

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.



51/1012