


Section 11 | 12 Twp 28S Rge 1 W Date Nov. 10, 1961



How was corner identified? From cut cedar BT

Condition of corner: Renewed with 1" tubular steel & 2 new BT's

Best route to reach corner: Spur road from Sec. 11
Black Cr. Road
New B.T.s

Other Remarks:

Quadrant	NE	NW	SE	SW
Species & Size		10" 1C	12" H	
Dist. & Bearing		29.2' NW	37.2' S11E	
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

51/218
 C. S. [unclear]
R. C. Grant
 Signed
Dec 28 07