

UNITED STATES PLYWOOD CORPORATION

P. O. BOX 1328 • ROSEBURG, OREGON • PHONE OR 2-3331



MANUFACTURERS OF WELDWOOD PLYWOOD AND ALLIED PRODUCTS

Section Corner: Sections 28, 29, 32, 33 T27S, R2W
Found: 1-1/2" iron pipe
15" Cedar, North 55° West, 19¹/₂ feet
Marked S29 BT

Set: 2-1/2" Aluminum Cap
9" Cedar, North 26¹/₂° East, 40⁵/₂ feet
Marked S28 BT
44" Douglas Fir stump, South 30° East, 61⁵/₂ feet
Marked S33 BT
48" Cedar Stump, South 01 West, 62¹/₂ feet
Marked S32 BT

December 1962

9 +

1/4 Section Corner: Sections 27 and 28 T27S, R2W
Found: 28" Douglas Fir Stump, North 84¹/₂° East, 14⁵/₂ feet
Marked 1/4 S27 BT
Set: 2¹/₂ Aluminum Cap
24" Douglas Fir Stump, South 28° West, 34⁵/₂ feet
Marked 1/4 S28 BT

December 1962

⊕



FILED
RECEIVED

APR 10 1963

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 51/254-3