

**UNITED STATES PLYWOOD CORPORATION**

P. O. BOX 1328 • ROSEBURG, OREGON • PHONE OR 2-3331



MANUFACTURERS OF WELDWOOD  
PLYWOOD AND ALLIED PRODUCTS

Section Corner: Sections 29, 30, 31, 32 T27S, R2W  
Found: 1½ Iron Pipe set in 1954 from original bearing trees.  
All trees have blown down or destroyed. I now replace  
iron pipe with 2½" aluminum cap and reference.

- Set: 2½ Aluminum Cap
- 7" Yew, South 39° West, 45.8 feet  
Marked S31 BT
- 15" Hemlock stump, North 03° East, 33.7 feet  
Marked S29 BT
- 17" Hemlock, North 51 West, 58.8 feet  
Marked S30 BT
- 16" Cedar, South 45° East, 14.9 feet  
Marked S32 BT

December 1962

✓ O

1/4 Section Corner: Sections 29 and 32 T27S, R2W  
Found:

- 15" Cedar, North 50° East, 11.2 feet  
Re-scribed: 1/4 S29 BT
- 9" Cedar, South 36° West, 19.2 feet  
Marked 1/4 S32 BT
- Set: 2½" Aluminum Cap

December 1962

✓ O

FILED  
RECEIVED

APR 10 1963

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

