

UNITED STATES PLYWOOD CORPORATION

P. O. BOX 1328 • ROSEBURG, OREGON • PHONE OR 2-3331



MANUFACTURERS OF WELDWOOD PLYWOOD AND ALLIED PRODUCTS

Section Corner: Section Corner 10, 11, 14, 15 T27S, R2W
Found: Original Stone
9" Douglas fir, South 40° East, 35.0 feet
15" Douglas fir, South 28° West (original S 21 W) 33.0 feet
Set: 2½" Aluminum Cap
9" Douglas fir, North 19° West, 34.1 feet
Marked S10 BT
6" Madrone, North 26° East, 24.6 feet
Marked S11 BT
Original 6" Madrone for S11 is gone.
Original 10" Live Oak, N59° West, for S10 is not legible. ✓ + O
December 1962

1/4 Section Corner: Sections 14 and 15, T27S, R2W
Found:
10" Yew, North 20° East, 38.3 feet
Set: 2½" Aluminum Cap
7" Yew, North 48½° West, 40.7 feet
Marked 1/4 S15 BT
Original Maple is gone. ✓ + O
December 1962

1/4 Section Corner: Sections 13 and 14, T27S, R2W
Found:
14" Cedar, North 22½° East, 19.3 feet
18" Cedar stump, North 72° West, 15.4 feet
Set: 2½" Aluminum Cap
December 1962 ✓ + O

FILED
RECEIVED
APR 10 1963
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

