

**UNITED STATES PLYWOOD CORPORATION**

P. O. BOX 1328 • ROSEBURG, OREGON • PHONE OR 2-3331



1/4 Section Corner: Sections 33 and 34, T27S, R3W

Found: 3/4" Iron Rod

This iron rod was set by me from the original bearing trees in 1955; subsequent logging destroyed all original bearings trees. I now scribe new bearing trees referring to the iron rod.

Set:

22" Cedar stump, South 78° West, 24.2 feet

Marked: 1/4 S33 BT RE4287

5" Hemlock, South 52° West, 52.6 feet

Marked: 1/4 S33 BT RE4287

12" Cedar, North 19° East, 71.1 feet

Marked: 1/4 S34 BT RE4287

December 1962 ✓ + ○

1/4 Section Corner: Sections 27 and 34, T27S, R3W

Found: 3/4 Iron Rod

10" Douglas fir, North 10° West, 11.9 feet (down)

Set: 2 1/2" Aluminum Cap


8" Douglas fir, South 33 1/2° East, 22.4 feet

Marked: 1/4 S34 BT

11" Douglas fir, North 65° East, 36.0 feet

Marked: 1/4 S27 BT

January 1963 ✓ + ○



FILED  
RECEIVED

APR 10 1963

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.