

**UNITED STATES PLYWOOD CORPORATION**

P. O. BOX 1328 • ROSEBURG, OREGON • PHONE OR 2-3331



MANUFACTURERS OF WELDWOOD  
PLYWOOD AND ALLIED PRODUCTS

1/4 Section Corner: Sections 10 and 11, T28S, R3W

Found: 3/4" Iron rod

Iron rod was set by me from original bearing trees in 1957. Subsequent logging destroyed all bearing trees. I now replace iron rod with 2-1/2 aluminum cap and reference.

Set: 2 1/2" Aluminum Cap


14" Cedar, South 31° West, 25.9 feet

Marked: 1/4 S10 BT

28" Douglas fir stump, North 23° East, 41.5 feet

Marked: 1/4 S11 BT

January 1963



FILED  
RECEIVED

APR 10 1963

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C. S. File No. 51/254-14