



How was corner identified? _____

Condition of corner: Replaced original Brass cap with ^{lost during road const.}

Brass Cap inscribed as follows: Placed 1' above ground.

Best route to reach corner: _____



Quadrant	NE	NW	SE	SW
Species & Size	15" D.F.			15" Hem
Dist. & Bearing	1051ks S67 1/2° W			731ks N3° E
Condition of Scribe	Good			Good
Original or Resurvey	Orig			Orig
Appearance of B.T.	Stump			Top out
Tags, Marks, etc.	Yellow BT Tag			Yellow BT Tag

Other Remarks:

~~APPROPRIATELY~~
 REGISTERED
 BOURBON
 LAND SURVEYOR

Wilford M. Aines
 MAY 7, 1948
 WILFORDS AINES
 239