

MENASHA CORPORATION



LAND AND TIMBER DIVISION

P. O. BOX 588 NORTH BEND, OREGON • 503 • 756-4136

March 3, 1965

Douglas County Surveyor
Roseburg, Oregon

Dear Sir:

Recently the following corners were re-established under my direction.

The South 1/4 corner of Section 19-T20S-R11W.

I find an old spruce B.T. now dead and windfell. I locate the corner from the spruce S34°W 16 links and drive a 2 inch X 2.5 ft. aluminum pipe 2 feet into the ground from which:

a 44 inch fir bears N53°W 44.0 ft. scribed S1/4 B.T. ⊕ #41✓

The corner to Sections 19, 20, 29 and 30, T20S, R11W.

I drive a 2 inch X 2.5 ft. aluminum pipe 2 feet into the ground from which:

A 35 inch fir bears S51°E 13.2 feet is an original B.T., now a stump with a face and an aluminum tag.

A 24 inch fir bears S55°W 4.0 feet, is an original B.T., now a stump with visible scribe.

I establish a new B.T. #42

A 44 inch fir bears N84°W 20.6 feet scribed S19 B.T. B.T. has a Forest Service Tag and a new BLM Tag. ⊕

The S 1/4 corner of Section 36-T20S-R12W

I drive a 2 inch X 3 ft. aluminum pipe 2 feet into the ground from which:

A 45 inch red cedar bears S31°E 11.9 feet is an original B.T. face has been chopped out.

I establish a new B.T.

A 34 inch fir bears N21½° E 35.0 feet scribed S36 B.T.

A 24 inch fir snag bears N17°W 23.7 feet with a tag and painted red.

Respectfully submitted for record.

Ronald L. Durham
LS #606

C. S. File No. 51/311

RLDLK
FOUNDED 1849

REGISTERED
OREGON
LAND SURVEYOR

JULY 12, 1963
RONALD L. DURHAM
606