

REN T 22SR8W CC 54/53

(ON S. LINE SEC. 33, T 21SR8W)

FD. BRASS CAP (1945 SURVEY)
IN GROUND. - HAD OBVIOUSLY BEEN
RECENTLY RESET. - DID NOT FIT
BEARINGS OR DIST. TO OLD BEARING
TREES. - 1 RESET IN PROPER
POSITION FROM 2 OLD B.T.'S.

FD. FIR TREE (NOW 54" DIAM.)
S62°W 25± FT. - PORTIONS OF OLD
SCRIBING VISIBLE ON BADLY BURNED
FACE.

FD. 32" FIR STUMP - CUT OFF
APPRX. 8 FT. ABOVE GROUND - S11¼°E
17± FT. - CUT OPEN & FIND GOOD SCRIBING
"W" ON OLD FACE.

REBLAZE & SCRIBE 54" DOUG. FIR
S62°W 25± FT. MKD. "T 22SR8W
CC S. 4 CS BT"

BLAZE & SCRIBE -
48" FIR STUMP N 32°E 78± FT.
MKD. "T 22SR8W CC S 3 S 4 CS BT"
NO LIVE TREES AVAILABLE.

FROM COR. AS RESET BY ME, THE
POSITION WHERE I FOUND CAP SET
BEARS N 38½°W 14± FT.

SEPT. 18, 1963

Milo C. Godfrey

M.G.
W.S.
M.S.

+ * ✓

(SEE D.C.F. File No. 52/14-28)