

REN. T 22 S R 8 W COR. $\frac{3}{2}$
SEC. 10/11

FD. 12" X 12" X 16" ROCK SET BY
COLE IN 1915. NO OTHER ROCKS IN
IMMEDIATE VICINITY. NO MKS. FD. OR ROCK.
FD. STUMP HOLE & ROTTEN REMNANTS
OF FIR STUMP N 36° W 28 1/2 FT.

FD. SLIGHT DEPRESSION - COULD BE
STUMP HOLE - N 50° E 29 1/2 FT.

FD. SLIGHT DEPRESSION - COULD BE
STUMP HOLE - S 23° E 33° FT.

NO TRACE OF S.W. B.T. FD. (LOCATION
FALLS IN ROADWAY)
(COLE'S NOTES STATE THAT
STUMPS WERE ALL THAT WAS LEFT
OF B.T.'S IN 1915.)

ALSO FD. YELLOW TAG ON FENCE
POST 48 FT. E. OF ROCK, STATING
THAT SEC. COR. WAS 48 FT. WEST OF TAG.
ALONGSIDE ROCK AT COR. SET
IRON PIPE WITH BRASS CAP MKD.
"COUNTY SURVEYOR'S OFFICE 1962
T 22 S R 8 W S 3 | S 2"
S 10 | S 11

BLAZE & SCRIBE NEW TREES:
8" DOUG. FIR N 41° E 34 1/2 FT.
MKD. "T 22 S R 8 W S 2 C S B T"
13" DOUG. FIR N 59° W 77 1/2 FT.
MKD. "T 22 S R 8 W S 3 C S B T"
7" DOUG. FIR S 33 1/2° W 57 1/2 FT.
MKD. "T 22 S R 8 W S 10 C S B T"

NO TREES AVAILABLE S, E, OF COR.
C. S. File No. 53/14-36

SEPT. 27, 1962
M.S.
M.S.

Milo E. Godfrey

+ X