

REN. - T 224 23 S R 9 W

N.E. COR $S 36$
SEC. 1 S1

FD. $1\frac{1}{2}$ " GALV. IRON PIPE AT COR.

FD. OLD, UPROOTED FIR TREE (NOW 32" DIAM.) N 88° W 19 $\frac{1}{2}$ FT. - TRACES OF OLD SCRIBING VISIBLE ON PREVIOUSLY OPENED FACE. "S" ONLY LEGIBLE.

FD. OLD, UPROOTED FIR TREE (NOW 30" DIAM. S 50° W 15 $\frac{1}{2}$ FT. - LYING FACE DOWN.

FD. FIR STUMP (NOW 40" DIAM.) N 20° E 15 $\frac{1}{2}$ - BARK FLAKING BADLY - NO MKS. VISIBLE.

FD. HOLLOW CHINQUAPIN SNAG (NOW 24" DIAM.) S 70° E 26 $\frac{1}{2}$ - BOTH UPPER & LOWER BLAZE VISIBLE ON BARK, BUT ENTIRE CENTER ROTTED AWAY.

COR. LIES ON TOP OF RIDGE.

DID NOT SET NEW COR. MONUMENT.

BLAZE & SCRIBE 2 NEW TREES;

13" WHITE FIR S 41° E 31 $\frac{1}{2}$ FT.

MKD. " T 22 S R 9 W S 36 CSBT "

12" WHITE FIR S 49° W 58 $\frac{3}{4}$ FT.

MKD. " T 23 S R 9 W S 1 CSBT "

MAR. 14, 1963

M. G.

V. T.

M. S.

Mil. E. Godfrey

C.S. File No. 52/19-54

T 224 23 S R 9 W