

FILED  
RECEIVED

FD. O.K.

FD. STANDARD. COR. SEC.'S 374  
ON N. BDRY. T 235 R 8 W 2 1963

BEARING TREES WERE SAME TREES  
USED AS B.T.'S - ~~COR.~~ <sup>CLUSTERS</sup> ~~COR.~~ <sup>COR.</sup>  
SEC.'S 374 (SEE RENEWAL <sup>ON OTHER SIDE</sup> ~~W/~~ <sup>ORE</sup>)  
I DID NOT RENEW COR. SINCE IT IS  
NO LONGER A COR. FOR ANY SECTION,  
AND IS LESS THAN 40 FT. FROM  
COR. RENEWED. ✓

FD. O.K.

1/4 S 33 1/2 S T 225 R 8 W

FD. GOV'T BRASS CAP & 2 NEW  
B.T.'S (1963 SURVEY) - COR. SET FROM  
ONE O.B.T. - W. OAK S 58° W 37 LKS. -  
OLD ROTTED FACE - NO SCRIBING VIS. ✓

FD. O.K.

CC S 33 | S 34 T 225 R 8 W

ON N. LINE T 235 R 8 W  
FD. GOV'T BRASS CAP & NEW B.T.'S  
(1963 SURVEY) - CAP IN FENCE  
COR. - OLD FIR STUMP APPROX. FITS  
BEARING & DIST. FOR ORIG. N.E. B.T. ✓

OCT. 2, 1963

*M. G. W. S.*

*Godfrey*

M. G.  
W. S.  
M. S.

CS 52/14-65

REGISTERED NO. 38519