

REN. T 22 S R 8W

INT. "L" CDR.  
D.L.C. #42

AT CDR. FD.  $\frac{1}{2}$ " IRON PIPE SET  
BY IRYING IN 1945.

FD. FIR STUMP N 86° W 21<sup>0</sup> FT. -  
SCRIBING VISIBLE "SW INT DLC 42"

FD. DOUG. FIR TREE (NOW 32" DIAM.)  
N 54° W (INSTEAD OF N 59° W) 76<sup>5</sup> FT. -  
VERY PLAIN AXE SCARS VISIBLE, -TREE  
IN GOOD CONDITION.

BLAZE & SCRIBE ONE NEW TREE:

21" DOUG. FIR N 5 $\frac{1}{2}$ ° E 76<sup>8</sup> FT.  
MHD. "INT L DLC 42 CS BT"

SEE REN. # 41

SEPT. 10, 1964

M.G.

W.S.

M.S.

*Phil E. Godfrey*

○  
+ X ✓

C. S. File No.

52/14 84