

REN. T 22 S R 8 W

INT. "L" COR.

D. L. C. 44

FD. DOUGLAS FIR (NOW 18" DIAM.)

N 38° E 13° FT. - SCRIBING VISIBLE
ON NOT COMPLETELY HEALED OVER
SCARS.

BRASS CAP NOT FD. - A SLIDE
HAS COVERED PORTION OF ROAD AT
THIS POINT - BRASS CAP PROBABLY
BURIED UNDER LOGS, ROCKS & DIAT.

NO TRACE FD. OF N.W. TREE
MKD. IN 1955 - IT IS ALSO PROBABLY
BURIED IN SLIDE.

AT COR. SET NEW IRON PIPE
WITH BRASS CAP MKD. "COUNTY
SURVEYOR'S OFFICE 1964 T 22 S
R 8 W INT "L" D. L. C. 44 T"

BLAZE & SCRIBE ONE NEW TREE:
15" DOUG. FIR N 45° W 17³/₄ FT.
MKD. "INT L DLC 44 CS BT"

SEE REN. # 46

SEPT. 1, 1964

M.G.

W.S.

M.S.

Wils E. Godfrey

+X ✓

C. S. File No. 52/14 67