

T 22 S R 7 W

W.C.

$\frac{S 15}{S 22}$

(BY GORDON & GARDNER-1963)

FD, DOUBLE CEDAR (50" DIAM.)

N $11\frac{1}{2}^{\circ}$ W 27 $\frac{1}{2}$ FT. SCRIBING VISIBLE
IN PREVIOUSLY OPENED SCAR-"T 22
R 7 W BT" CEDAR HAS BEEN DEAD
FOR SEVERAL YRS.

FD, REMAINS OF CEDAR STUMP

S $47\frac{1}{2}^{\circ}$ W 38 $\frac{3}{4}$ FT. UPROOTED & CENTER
ROTTED AWAY - NO SCARS OR SCRIBING

FD

AT COR. SET IRON PIPE WITH
BRASS CAP MKD. "COUNTY SURVEYOR'S

OFFICE 1962 T 22 S R 7 W W.C. $\frac{S 15}{S 22}$

BLAZE & SCRIBE NEW TREES:

8" DOUGLAS FIR S 86° W 28 $\frac{1}{2}$ FT.

MKD. "W.C. S 22 CS BT"

6" DOUGLAS FIR N 46° W 24 $\frac{3}{4}$ FT.

MKD. "W.C. S 15 CS BT"

Mar. 2, 1962

M.G.

V.T.

C.A.

Milo C. Coffey

+ * 1

C. S. File No.

52/14 422