

REN. T 21 S R 9 W

COR. SECS. $\frac{17}{16}$
 $\frac{20}{21}$

FD. ROCK AT COR. - MKD. AS
DESCRIBED.

FD. FIR TREE (NOW 45" DIAM.)
N 40° W 59 FT. - SHOWS GOOD SCAR.

FD. FIR TREE (NOW 44" DIAM.)
N 19° E 178 FT. - SHOWS GOOD SCAR.

FD. FIR TREE (NOW 24" DIAM.)
S 49° E 607 FD. - VERY PLAIN SCAR.

FD. FIR TREE (NOW 45" DIAM.)
S 59° W 564 FT. - SCAR HAS BEEN
DESTROYED BY INJURY.

ALONGSIDE ROCK AT CORNER
SET IRON PIPE WITH BRASS CAP
MKD. "COUNTY SURVEYOR'S OFFICE
1964 T 21 S R 9 W S 17 | S 16 "

S 20 | S 21

BLAZE & SCRIBE ONE NEW TREE:
14" HEMLOCK S 58 1/2° W 49 FT.
MKD. "T 21 S R 9 W S 20 CS BT"

OCT. 20, 1964

Milo E. Godfrey

M.G.
W.S.
M.S.

TX ✓

(SEE OVER.) File No. 52/14 -135