

Renewal

SW/DLC #55 - 22588W

Found

18" Oak Non-stump N4W 493°

Scribe found "BT"

No Trace of SW BT.

Renewal

Set 2" x 30" I.P.P. at cor -

New Bearing Trees

9" W. Oak N31½E 23½  
Scribed SW/DLC 55 CS BT

13" D. Fir N72E 13°  
Scribed SW/DLC 55 CS BT

Fence cor Running N + E N33E C<sup>+</sup>

Note

old cor Fence Post lies in Bottom of Ravine where cor is. Mr Garrison confirms that it was old cor post and that our 2" Iron pipe is where cor should be.

I do not set Brass cap because cor falls in Ravine full of Water, No water in Summer, Maybe Brass can be set at that time.

D.K.  
J.W.M.

1-12-72

*[Handwritten signature]*

#126 ✓

C. S. File No. 52/14-139

DIETZEN NO. 385-6