

RENEW  $\frac{1913}{2329}$

T 31 S R 6 W

FOUND - ORIG. 8" NOW 10" LAUREL  
S 20' W 13.2 SHOWS GOOD SCRIBING  
ORIG. 36 NOW 46" FIR S 71° E 18.5  
NO SCRIBING FOUND  
50' R. FIR N 32° E 29.7' SHOWS SCAR  
WE DO NOT FIND N W BT

SET BRASS CAP AT CORNER  
MND. COUNTY SURVEYORS OFFICE

1962  $\frac{514513}{523524}$

T 31 S R 6 W

NOTE - COR IS 50' SOUTH OF  
LOG ROAD

NEW BTS.

RESURIBE O.B.T. NOW 46" R. FIR  
S 73° E 21.5 29 T 31 S R 6 W CS BT

8" R. FIR BEING  
SCRIBED S 23  $\frac{12}{12}$  S 72° W 33.2  
31 S R 6 W CS BT

NO TREES NEAR TO NW.

AUG 30-62

VAR 20  $\frac{1}{2}$ °

HIGGS  
BRIS  
36.5  
5.5

+ \* ✓

C. S. File No. 52/25-13

80-23

TWP 31

Rge

6

N

Date: 8-29-63



How was corner identified? 1 BT, AND MOUND OF

STONES

Condition of corner: POOR CONDITION, ABOUT 70

BE EAST

Best route to reach corner: RUSSELL CREEK ROAD T.

SOUTH CENTER OF SEC 13, TURN RIGHT ON  
BLM. ROAD WHICH PASSES WITHIN 30' OF CORNER

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tools, Marks, etc.				

Handwritten notes in the table cells:

- Under NW: 10'
- Under SE: 10'
- Under SW: 3'
- Large handwritten 'A' or 'P' in the middle of the table.

Vicki Olson

Signed,

CS 52128-13