

REN. T 25 S R 1 W COR. 10 | 11
SECS. 15 | 14

FD. $\frac{3}{4}$ " IRON REINFORCING ROD
AT COR.

FD. DOUG. FIR (NOW 26" DIAM.)
N 65° W 7 $\frac{3}{4}$ FT. SHOWS 2 VERY PLAIN
AXE SCARS, DID NOT OPEN.

FD. DOUG. FIR (NOW 32" DIAM.)
N 79° E 8 $\frac{6}{8}$ FT. SHOWS 2 VERY PLAIN
AXE SCARS, DID NOT OPEN.

FD. STUMP & SPROUTS OF DOG-
WOOD S 70° E 5 $\frac{9}{8}$ FT.

NO TRACE OF CHINQUAPIN TO SW.

FD.

BLAZE & SCRIBE 2 NEW TREES:

16" RED CEDAR S 1° W 22 $\frac{8}{8}$ FT.

MKD "T 25 S R 1 W S 15 C S BT"

14" RED CEDAR S 26° E 40 $\frac{2}{8}$ FT.

MKD. "T 25 S R 1 W S 14 C S BT"

JUNE 7, 1962

M.G.

V.T.

C.P.

Mils

[Signature]

+XV

C. S. File No. 52/30-8