

REM T 25 S R 1 W $\frac{1}{4}$ S 1 S
10 11

F.D. $\frac{3}{4}$ " REINFORCING ROD IN
MOUND OF ROCK AT COR.

F.D. CEDAR TREE N 72° W 18⁵ FT
DOWN & BADLY ROTTED. FAINT PORTIONS
OF SCRIBE MARKS BARELY VISIBLE ON
BADLY ROTTED FACES (2 FACES)

F.D. ROTTED REMNANTS OF HEMLOCK
STUMP S 70° E 16⁵ FT - TOO FAR
GONE TO FIND ANY MARKS.

BLAZE & SCRIBE 2 NEW TREES:

14" HEMLOCK S 64° W 20⁺ FT.
MKD. " $\frac{1}{4}$ S 10 C S BT"

11" DOUG. FIR N 23° E 31^D FT.
MKD. " $\frac{1}{4}$ S 11 C S BT"

COR. LIES APPROX. 200 FT.
WEST OF CANTON CREEK

JUNE 7, 1962

M.G.

V.T.

C.P.

M.G.

C.P.

+ * r

C. S. File No. 52/30-10