

FD. T 25 S R 1 W

COR.
SECS.

23 | 24
26 | 25

AT COR. FD. $3/4$ " IRON REINFORCING
ROD, DID NOT FIND ROCK CALLED FOR
IN GOV'T NOTES.

ALL ORIG. B.T.S ALIVE & STANDING,
VIS:

5" HEMLOCK (NOW 8" DIAM.)
S 75° W 9 $\frac{1}{2}$ FT. PREVIOUSLY DRENED
& SCRIBING VISIBLE.

6" HEMLOCK (NOW 8" DIAM.)
N 61° W 14 $\frac{1}{2}$ FT. SHOWS GOOD SCAR.

5" HEMLOCK (NOW 6" DIAM.)
S 43° E 7 $\frac{3}{4}$ FT. SHOWS GOOD SCAR.

10" WHITE FIR (NOW 17" DIAM.)
N 35° E 12 $\frac{1}{2}$ FT. SHOWS 2 GOOD SCARS.

COR. & B.T.S IN GOOD CONDITION.

COR. LIES ON E. SLOPE APPROX.
150 FT. WEST OF S. END OF
BRIDGE ON CANTON CREEK ROAD,

NOV. 7, 1962

Mils E. Coffey

M.G.
VT.
M.S.

OT* ✓
C. S. File No. 52/30-13