

515 514  
Renew Sec. COR. 522 523 T255 R1W

Fd. 1962 C.S. BRASS Cap properly

Mkd. & B.T.s as follows - see Ren. #41

15" R. cedar N. 62°W. 29 ft.

alive - scribe visible on unhealed blaze.

38" R. cedar S. 79½°E. 9 ft.

alive - scribe visible on upper blaze -

Lower blaze burned - Rescribe "BT"

This tree also orig. B.T. - S.W. Ren. B.T.

down & out of place. other orig

B.T.s destroyed in logging. we mark

New B.T.s -

5" Hemlock N. 60°E 85 ft.

Mkd "514 CS BT"

24" D Fir (stump) S. 40°W 63 ft.

Mkd. "T255 R1W 522 CS BT"

This cor lies approx 200 ft West.

of Road at cutting cor., Timber

in sec. 15 only.

FILED

RECEIVED

U.A.T.

J.H.

D.W.

OCT 27 1966

*R. J. [Signature]*  
COUNTY SURVEYOR  
DOUGLAS COUNTY, OREGON

194  
X O.K. J.W.B.

C.S. File No. 52/30-38