

Review $\frac{1}{4}$ 523 ^{ESICS} 522 T255 RIW

Fd. 1962 CS. BRASS cap properly
MKd. & set with B.T. 25 follows -

See Ren. #39 -

orig. N.E. B.T. still remains & broken
off.

9" Hemlock S. 33° W. 11 $\frac{3}{4}$ ft.

alive - severely injured & nearly turned out
shows SCRIBE on unhealed blaze.

18" Fir N. 35° E. 37 $\frac{3}{4}$ ft.

alive & good cond. - SCRIBE visible on
unhealed blaze, use MK new B.T.

50" D. Fir (stump) N. 44° W. 21 $\frac{3}{4}$ ft.
MKd. " $\frac{1}{4}$ 522 CS BT"

This COR. Lies on East edge clearcut
unit approx. 50 ft. N.E. of Road
Junction -

OCT. 27, 1966

V.R.T.
J.H.
D.W.

FILED

RECEIVED

OCT 27 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C.S. File No. 52/30-39

* #493
O.K. J.W.B.