

Renew Sec. Cor.  $\frac{59}{516} | \frac{510}{515}$  T255 RIW

Fd.  $1\frac{1}{2}$ " I.P. & one Live BT 25 Recorded in

Ren. # 33 & Remains of orig. B.T.s 25 Follows-

Ren. B.T. - 8" Now "Hemlock N.  $58\frac{1}{2}$ °E. 29 $\frac{3}{4}$  ft,

Not 27 $\frac{3}{4}$  ft.-

Orig. 12" Now 16" Fir N. 50°E. 17 $\frac{8}{16}$  ft.

Now decayed stump - find Ave MKs. only

Orig. 14" Now 16" Fir S. 61°E. 29° ft

Now decayed stump - find "BT" scribe

All other B.T.s down or gone. Note,

did not set Brass cap. - MK. New B.T.s. -

11" R. cedar S. 74°E. 49 $\frac{5}{16}$  ft,

Mkd. "T255 RIW S15 CS BT"

6" Hemlock S. 79°W. 7 $\frac{8}{16}$  ft.

Mkd. "S16 CS BT"

No trees available to NW. - This

Cor. Lies on N.-S. cutting line

cutoff to West.

Nov. 7, 1966

FILED

RECEIVED

V.R.T.

J.H.

D.W.

C.S.

NOV 7 1966

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

#91  
K

O.K. J.V.S.

C. S. File No. 52/30-53