

519 | 520  
Renew Sec. COR. 530 | 529 T255 RIW

Fd. O.B.T.s as follows -

ORIG. 7" Now 9" FIR S. 51° W. 11 ± ft.

Now Badly decayed STUMP - Find Fragmentary  
Scribe.

ORIG. 7" Now 9" FIR N. 77° W. 9 ± ft.

Now Badly decayed STUMP - Find "BT" scribe.

No Trace other O.B.T.s - also find B.T.s

Recorded in Ren. # 11 by Hosford -

16" FIR N. 68½° E. 12 ± ft.

2 live - healed blaze.

18" FIR S. 68½° E. 8 ± ft.

2 live - scribe visible on nearly healed blaze.

28" FIR S. 49° W. 32 ± ft.

2 live - with healed blaze.

22" FIR N. 44½° W. 5 ± ft.

2 live - healed blaze. all face

measurements to Hosford's B.T.s. set

1" I.P. & BRASS CAP MKD. "COUNTY

SURVEYOR'S OFFICE 1967 T255

519 | 520  
530 | 529 RIW" - do not find Rock

called for. COR. lies on very steep  
northerly slope on spur.

May 10, 1967

V.R.T.  
J.H.  
D.W.

*[Signature]*  
R 519

O.C.S. File No. 8 52/30 -84