

RENEW $\frac{1}{4}$ COR 29 T 24S R 1W
32

FOUND - ORIG 12" NOW 14" CEDAR NORTH
29' SHOWS GOOD SCRIBING " $\frac{1}{4}$ "
12" NOW PARTLY ROTTED STUMP
SHOWS GOOD SCRIBING " $\frac{1}{4}$ " S 21° E 25.1

SET BRASS CAP AT CORNER MND.
COUNTY SURVEYORS OFFICE 1960
T 24S R 1W

NEW BTS.

12" HEMLOCK BEARS S 10° E 33.4
SCRIBED $\frac{1}{4}$ S 32 CS BT.

1" HEMLOCK BEARS N 10° W 27.1
SCRIBED $\frac{1}{4}$ S 29 CS BT

✓✓
RENEW $\frac{29}{32}$ T 24S R 1W
32/33

FOUND - THREE ORIG BTS
CHECK BEARING & DIST. SW BT
GONE NE & NW SHOW SCRIBING
BT SHOWS GOOD FACE BUT NO
SCRIBING. I SCRIBE THIS BT, S 28° E
16.5' 16.5', S 33 T 24S R 1W.

NOTE E LOG ROAD N 44° W 13'

SET BRASS CAP AT COR MND.
COUNTY SURVEYORS OFFICE 1960

$\frac{29}{32}$ T 24S R 1W
 $\frac{32}{33}$

15" PINE BEARS S 54° W 27.9'
SCRIBED 32 T 24S R 1W CS BT

✓✓ C. S. File No. 53/42-1