

REN. T 24 S R 1 W 28/27

FD. MOUND OF ROCKS AT
COR. 33/34

FD. FIR TREE (NOW 24" DIAM.)

N 68° E 22¹/₂ FT. (INSTEAD OF N 66° E) 22¹/₂ FT.)

SHOWS GOOD SCARS. TREE IN GOOD CONDITION.

FD. CHINQUAPIN (NOW 8" DIAM.)

S 29° E 5³/₈ FT. (INSTEAD OF S 34° E) 5³/₈ FT.

FACE BADLY ROTTED BUT SCRIBING "BT"
VISIBLE.

FD. PINE TREE (INSTEAD OF FIR)

(NOW 24" DIAM.) S 42° W (INSTEAD OF S 41° W)

17³/₈ FT. SHOWS SCARS. BLAZE & RESCRIBE
THIS TREE "T 24 S R 1 W S 33 C S BT."

N.W. B.T. NOT FD.

AT COR. SET IRON PIPE WITH BRASS
CAP MKD. "COUNTY SURVEYOR'S OFFICE

1961 T 24 S R 1 W S 28/527
33/34

BLAZE & SCRIBE TWO NEW TREES:

17" DOUGLAS FIR N 32¹/₂° W 24³/₈ FT.

MKD. "T 24 S R 1 W S 28 C S BT"

13" DOUGLAS FIR S 47¹/₂° E 26³/₈ FT.

MKD. "T 24 S R 1 W S 34 C S BT"

OCT. 3, 1961

Milo E.

W. C. Coffey

M. G.
V. T.

File No.

52/42⁷

+ * ✓